



Armaduras de distribuição	
Armadura	Armadura de distribuição
N1	12 N2 ø5.0 c20 C=40
N6	6 N2 ø5.0 c20 C=103
N4	4 N2 ø5.0 c20 C=41
N2	12 N2 ø5.0 c20 C=42
N8	12 N8 ø5.0 c20 C=72
N6	22 N6 ø5.0 c20 C=70
N10	22 N11 ø5.0 c20 C=50
N20	38 N13 ø5.0 c13 C=24
N70	38 N14 ø5.0 c13 C=21
N15	22 N17 ø5.0 c20 C=169
N4	20 N18 ø5.0 c20 C=97
N19	5 N21 ø5.0 c20 C=45
N22	25 N18 ø5.0 c20 C=97
N65	25 N23 ø5.0 c20 C=149
N24	4 N25 ø5.0 c20 C=410
N28	3 N25 ø5.0 c20 C=410
N27	3 N28 ø5.0 c20 C=80
N27	3 N29 ø5.0 c20 C=169
N31	3 N30 ø5.0 c20 C=131
N27	3 N29 ø5.0 c20 C=169
N27	3 N29 ø5.0 c20 C=169
N31	4 N32 ø5.0 c20 C=95
N31	4 N33 ø5.0 c20 C=99
N31	4 N34 ø5.0 c20 C=136
N31	4 N35 ø5.0 c20 C=144
N31	4 N36 ø5.0 c20 C=177
N31	4 N37 ø5.0 c20 C=162
N31	4 N38 ø5.0 c20 C=159
N31	4 N39 ø5.0 c20 C=89
N31	4 N40 ø5.0 c20 C=169
N31	4 N3 ø5.0 c20 C=103
N31	4 N41 ø5.0 c20 C=118
N31	4 N42 ø5.0 c20 C=173
N31	4 N21 ø5.0 c20 C=43
N31	4 N43 ø5.0 c20 C=51
N31	4 N42 ø5.0 c20 C=173
N31	4 N44 ø5.0 c20 C=95
N31	4 N45 ø5.0 c20 C=122
N31	4 N46 ø5.0 c20 C=159
N27	3 N47 ø5.0 c20 C=89
N31	4 N49 ø5.0 c20 C=142
N31	4 N50 ø5.0 c20 C=153
N31	4 N42 ø5.0 c20 C=173
N27	3 N53 ø5.0 c20 C=110
N27	3 N53 ø5.0 c20 C=151
N31	4 N53 ø5.0 c20 C=191
N31	4 N54 ø5.0 c20 C=162
N31	4 N55 ø5.0 c20 C=142
N31	4 N56 ø5.0 c20 C=129
N31	4 N57 ø5.0 c20 C=201
N31	4 N58 ø5.0 c20 C=486
N31	4 N59 ø5.0 c20 C=61
N31	4 N60 ø5.0 c20 C=54

